

Appendix B: Subject Property Images

Exterior Images of Structures



Image 1: View to Subject Property from Cedar Springs Road
(Photo taken on November 13, 2019; Facing South)



Image 2: Farmhouse Façade, 5780 Cedar Spring Road, Burlington
(Photo taken on November 13, 2019; Facing South)



Image 3: Northeast Corner of Farmhouse
(Photo taken on November 13, 2019; Facing Southwest)



Image 4: Detail of Farmhouse Stone Foundation
(Photo taken on November 13, 2019; Facing Southwest)



Image 5: East Elevation of the Farmhouse
(Photo taken on November 13, 2019; Facing West)



Image 6: Detail of the Farmhouse Windows
(Photo taken on November 13, 2019; Facing West)



Image 7: Southeast Corner of the Farmhouse
(Photo taken on November 13, 2019; Facing Northwest)



Image 8: South Elevation of the Farmhouse
(Photo taken on November 13, 2019; Facing North)



Image 9: Southwest Corner of the Farmhouse
(Photo taken on November 13, 2019; Facing Northeast)



Image 10: West Elevation of the Farmhouse
(Photo taken on November 13, 2019; Facing East)




Image 11: Detail of Gable Peak in West Elevation of Farmhouse
(Photo taken on November 13, 2019; Facing East)



Image 12: Detail of Porch leading to South Addition to Farmhouse
(Photo taken on November 13, 2019; Facing West)