

Appendix B of PL-61-22- Photographs



Ice House Exterior (2022)



2018 Exterior Photo



Ice House Interior



Broken window in gable end



Main house south (front) elevation before the fire (2020)



Main House east (side) before the fire (2020)



Demolished main house after the fire -View south towards Burlington Bay



Cabana Building (No heritage significance)



Accessory Building #1



Accessory Building #2 (No heritage significance)