

Site:	603 Woodland Avenue
-------	---------------------

Existing Tree Information					Replacement Tree Information	Condition Factors	Total Caliper Replacement (cm)	# of 50mm trees required	Cash-in-lieu required	
Tree Number	Common Name	DBH (cm)	Condition Rating (%)		Comments	Total cm to Replace	Avg Condition Rating (Health & Structure)			
			Health	Structure						
1	Red Fox Katusra	19	70%	35%	M1	10.0	53%	10	2	\$ 1,000.00

1. Total cm to replace is based on average condition rating and size of the tree
2. # of trees req. to be replaced is based on a 50mm caliper replacement
3. Cash-in-lieu of replacemet is based on \$500 / replacement tree required

Tree Condition Considerations

Based on Tree Condition Assessment

Rating:	Factor:
Excellent	90-100%
Good	70-89%
Fair	50-69%
Poor	25-49%
Very Poor	0-24%