

Photographs (PL-54-24)

Photographs

All images taken by City of Burlington on May 31, 2024.



Figure 1: Front Window and Door Opening



Figure 2: West Portion of Front Elevation

Appendix B – Photographs (PL-54-24)



Figure 3: Side (West) Elevation of Subject Building



Figure 4: Single-Storey Rear Addition, (West) Elevation

Appendix B – Photographs (PL-54-24)



Figure 5: Northwest Corner of Single-Storey Rear Addition

Appendix B – Photographs (PL-54-24)



Figure 6: Landscaped Area to the East of the Subject Building